

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/01/2017

Submitted Date:

06/01/2017

Document Number:

685303218**FIELD INSPECTION FORM**Loc ID 326060 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 19160Name of Operator: CONOCO PHILLIPS COMPANYAddress: P O BOX 2197City: HOUSTON State: TX Zip: 77252-**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Brock, Christine		Christine.Brock@conocophillips.com	SW Inspection Reports
Walker, Crystal	505-326-9837	Crystal.Walker@cop.com	SW Inspection Reports
Prasanna, Sonu	832-486-2299	Sonu.Prasanna@conocophillips.com	SW Inspection Reports
Busse, Dollie	505-324-6104	dollie.l.busse@conocophillips.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215798	WELL	PR	09/18/1990	GW	067-07403	BONDAD 33-10 COM 104	PR

General Comment:[See link at end of report to path for downloadable pictures.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		,	
Comment:	Tank is missing 2 gauge hatch covers and has another opening large enough for wildlife entry point. Corrective action not complete. Corrective action date remains the same to track days of noncompliance.					
Corrective Action:	Repair or replace hatches and seal opening to prevent wildlife from entering tank to comply with Rule 201.					Date: 05/13/2017

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	Not labeled	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment:	Grass is growing inside bermed area. Corrective action not complete. Corrective action date remains the same to track days of noncompliance.			
Corrective Action:	Repair or install berms or other secondary containment to comply with Rule 605.a.(4).			
				Date: 05/13/2017

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401298396	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160921
685303219	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160897
685303220	Produced water tank missing hatches and plugs.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160898
685303221	Missing thief hatch.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160899
685303222	Missing thief hatch and connections missing plugs.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160900
685303223	Grass growing inside containment berms.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160901
685303224	Grass growing along edge of liner.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160902