

Inspection Photos

6/7/2017

Operator: PDC ENERGY INC - 69175

Location ID: 319218

Inspection Doc. Number: 682502162

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 319218



Photo 1: Photo taken from the south end of the location, facing northwest. Photo shows location has had surface roughening implemented. Surface roughening is a temporary BMP that should be used in conjunction with other BMPs. Photo also shows no perimeter BMP controls have been installed.



Photo 2: Photo taken from the south end of the location, facing north. Photo shows location has had surface roughening implemented. Surface roughening is a temporary BMP that should be used in conjunction with other BMPs. Photo also shows no perimeter BMP controls have been installed.

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 319218



Photo 3: Photo taken from the south end of the location, facing northeast. Photo shows location has had surface roughening implemented. Surface roughening is a temporary BMP that should be used in conjunction with other BMPs. Photo also shows no perimeter BMP controls have been installed.



Photo 4: Photo taken from the south end of the location, facing east. Photo shows location has had surface roughening implemented. Surface roughening is a temporary BMP that should be used in conjunction with other BMPs. Photo also shows no perimeter BMP controls have been installed.

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 319218



Photo 5: Photo taken from the west end of the location. Photo shows area where a compaction test pit was dug. 6 foot measuring stick for reference.

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 319218



Photo 6: Photo of compaction test pit from the west end of the location. Photo shows compaction layers found in the first 9 inches of soil.



Photo 7: Photo of compaction test pit from the west end of the location. Photo shows compaction layers found in the first 9 inches of soil.

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 319218



Photo 8: Photo taken from the east end of the location. Photo shows area where a compaction test pit was dug. 6 foot measuring stick for reference.



Photo 9: Photo taken from the east end of the location. Photo shows compaction layers found in the first 12 inches.