

# Inspection Photos

6/8/2017

Operator: EDDY OIL COMPANY - 26420

Location ID: 322675

Inspection Doc. Number: 682502199

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: EDDY OIL COMPANY - 26420  
Location ID: 322675



**Photo 1:** Photo taken from the northeast end of the location, facing south. Photo shows large areas of the location remain bare and unvegetated. Location is not progressing towards COGCC 1000 series reclamation standards.



**Photo 2:** Photo taken from the northeast end of the location, facing southwest. Photo shows large areas of the location remain bare and unvegetated. Location is not progressing towards COGCC 1000 series reclamation standards.

Inspection Photos  
Operator: EDDY OIL COMPANY - 26420  
Location ID: 322675



**Photo 3:** Photo taken from the northeast end of the location, facing west. Photo shows large areas of the location remain bare and unvegetated. Location is not progressing towards COGCC 1000 series reclamation standards.



**Photo 4:** Photo taken from the center of the location, facing west. Photo shows large areas of the location remain bare and unvegetated. Location is not progressing towards COGCC 1000 series reclamation standards.

Inspection Photos  
Operator: EDDY OIL COMPANY - 26420  
Location ID: 322675



**Photo 5:** Photo taken from the adjacent reference area, facing east. Photo shows vegetation over the reference area.

Inspection Photos  
Operator: EDDY OIL COMPANY - 26420  
Location ID: 322675



**Photo 6:** Photo taken from the tank battery south of the location. Photo shows riser located on the northwest corner of the horizontal separator. Riser does not have the required markings, or lockout/tagout required per the May 2, 2017 Flowline or Pipeline NTO. Riser will need to be removed per Phase II of the NTO.