

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2017

Submitted Date:

06/08/2017

Document Number:

674901676**FIELD INSPECTION FORM**Loc ID 325128 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 26625Name of Operator: ELM RIDGE EXPLORATION COMPANY LLCAddress: 12225 GREENVILLE AVE STE 950City: DALLAS State: TX Zip: 75243-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Archuleta, Amy		aarchuleta@elmridge.net	
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	<a href="#">SW Inspection Reports</a>
Fischer, Alex		alex.fischer@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115631	PIT		09/23/1999		-	MCELVAIN DAKOTA 1	
214072	WELL	PR	10/01/2012	GW	067-05373	MCELVAIN DKTA UNIT 1	EI

**General Comment:**

On May 23, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge McElvain Dakota #1. For the most recent field inspection report for this facility, please refer to document #685303002. West Environmental Supervisor Alex Fischer and Catamount representative Jacob Franchini were on location during this inspection.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	El Paso carsonite pipeline marker.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Operator contact information posted on well head sign.

Corrective Action: Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:	Post and wire fencing surrounding bermed area.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Pipeline riser and valve		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	115631	Type:	PIT	API Number: -	Status:		Insp. Status:		
Facility ID:	214072	Type:	WELL	API Number:	067-05373	Status:	PR	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType:  Lined: NO Pit ID: 115631 Lat: 37.092739 Long: -107.764015Reference Point:  Other:  Length:  Width: **Lining:**Liner Type:  Liner Condition: Comment: 

Corrective Action

**Contact COGCC EPS staff for directives per Rule 905.b.**Date: 06/19/2017c**Fencing:**Fencing Type: Livestock Fencing Condition: AdequateComment: 

Corrective Action

Date: **Netting:**Netting Type:  Netting Condition: Comment: 

Corrective Action

Date: Anchor Trench Present:  Oil Accumulation:  2+ feet Freeboard: Comment: 

Corrective Action

Date: **COGCC Comments**

Comment	User	Date
On May 23, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge McElvain Dakota #1. For the most recent field inspection report for this facility, please refer to document #685303002. COGCC West Environmental Supervisor Alex Fischer and Catamount representative Jacob Franchini were on location during this inspection. This site visit was in response to corrective action noted in previous inspection regarding pit/bermed area. COGCC staff directed Catamount representative to submit a Site Investigation and Remediation Workplan for pit closure.	hughesj	06/08/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901677	Pit/bermed area.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166077">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166077</a>
674901678	Riser and valve.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166078">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166078</a>
674901679	Meter house and pipeline risers.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166079">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166079</a>