



OW RPT	OW CMT	WELLBOR	CMT	WL
	80		80	80
tg 376	376		736	376
265 sx	265 sx		265	
	1400		1400	1400
	1500	1500	1500	
	4026		4026	4026

6244 6244

70 SX	70 sx		70 sx	
-------	-------	--	-------	--

7470	7470	7470	7470	7470
------	------	------	------	------

**COLOR KEY**



<b>GENERAL INPUTS</b>	
Name	Elizabeth Hunt
Cell Phone Number	808-594-3092
Date	6/5/2017
<b>WELL INPUTS</b>	
Well Name	Guest 11-13A
API #	05-123-20962
WINS #	75408
Gyro Date:	Sept 2011
Surface Hole Size (in)	12.25
Prod Hole Size (in)	7.88
OH Excess Factor	60
Surface Casing (size/wt)	8-5/8", 24#
Surface Casing Shoe (ft)	942
Prod csg (size/wt)	4.5", 11.6#
Tubing OD (in)	2-3/8"
Tubing Set Depth (ft)	7530
Collar Above CIBP (ft)	7454
Collar Below CIBP (ft)	7496
Niobrara CIBP / BOC (ft)	7470
Niobrara TOC (ft)	6480
Niobrara Cement Vol (sx)	60
SUSX/SH BOC (ft)	4425
SUSX/SH TOC (ft)	4020
SUSX/SH Cement Vol (sx)	30
Bradenhead Issues? (Y/N)	N
Stub Plug BOC (ft)	1500
Cut Casing Depth (ft)	1400
Stub Plug TOC Form6 (ft)	892
Stub Plug TOC Calc (ft)	742
Stub Plug Cement Vol (sx)	220
<b>GEOLOGY INPUTS</b>	
FHM (ft)	1286
Sussex Top (ft)	4221
Sussex Base (ft)	4544
Shannon Base (ft)	Absent
Niobrara Top (ft)	6881
<b>QUESTIONS?</b>	
Who Drilled Well?	APC
Straight or Deviated Hole?	Straight
Age of well (yr)	14
Any squeeze holes? (Y/N)	N
Details of Integrity Issues?	DV Tool @ 4850'
SUSX/SH Productive? (Y/N)	N
Gyro Found (Y/N)	Y
CBL Found (Y/N)	Y
Packer Downhole? (Y/N)	N
Packer Depth (ft)	NA

\*If No Integrity Issues, Put "NONE".