

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2017

Submitted Date:

06/02/2017

Document Number:

681700524**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 320206 Arauza, Steven 2A Doc Num: _____

Operator Information:OGCC Operator Number: 87195Name of Operator: TEXAS TEA OF COLORADO LLC DBA TEXAS TEA LLCAddress: 14405 W. COLFAX #298City: LAKEWOOD State: CO Zip: 80401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203037	WELL	SI	06/04/2012	OW	001-08443	R C NAUMAN 4	EI

General Comment:

COGCC environmental unit inspection to document existing conditions at orphaned facility. Operator's registration and right to conduct oil and gas operations in the state of Colorado were revoked under COGCC OFV 1V-573.

LocationOverall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	Ward petroleum signs at battery.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign has been marked with COGCC emergency contact info.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Uncontrolled weeds at wellhead.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: Localized, oil-stained soil at wellhead (see photos).

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 9		
Comment:	NOT IN USE: Nine (9) steel flowline risers located at former tank battery. COGCC has had flowlines tagged and painted to comply with 2017 Flowline NTO.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 203037 Type: WELL API Number: 001-08443 Status: SI Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401298774	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4161255
681700536	Field Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4161253