

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/01/2017

Submitted Date:

06/02/2017

Document Number:

682600308**FIELD INSPECTION FORM**
 Loc ID 439367 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10412Name of Operator: AUS-TEX EXPLORATION INCAddress: 113 N SANTA FECity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Goss, Aaron	303-233-2232/303-495-0327	AGoss@austinexploration.com	All Inspections
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@austinexploration.com	All Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439366	WELL	SI	06/08/2016	OW	043-06227	Columbus 1	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Operator has improperly stored fluids and non E&P waste leaking on location (see attached photos).

At the time of inspection on 6/1/2017 sediment control BMPs were not installed correctly. Straw wattles have been laid on top of ground, are inadequately staked and will allow runoff to flow under the BMPs.

Environmental**Spills/Releases:**

Type of Spill: NON E&P WASTE

Estimated Spill Volume: _____

Comment: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Corrective Action: Operator shall clean up spill within 48 hours.

Date: 06/04/2017

Reportable: NO

GPS: Lat 38.314800

Long -105.150702

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Pursuant to Rule 1002.f., Aus-Tex Exploration Inc. shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control storm water runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

At the time of inspection on 6/1/2017 sediment control BMPs were not installed correctly. Straw wattles have been laid on top of ground, are inadequately staked and will allow runoff to flow under the BMPs.

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 06/30/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Follow up inspection required to document spill cleanup and proper installation of sediment control BMPs.	kosolaj	06/02/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401299297	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4161678
682600314	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4161660