

Inspection Photos
Location Name: Westward 2
API #069-06103



Photo 1. Tank battery looking east. Note tanks are visible from Hwy 287 are not painted as required. No NFPA label on oil tank.




Photo 2. Water vault lid not in place. Wildlife entrance possible. Unmarked 2" poly riser.

Inspection Photos
Location Name: Westward 2
API #069-06103



Photo 3. No NFPA label on water vault. Contents and capacity stenciled on top, but not readily visible from outside of berm



Photo 4. Signage for water vault not readily visible

Inspection Photos
Location Name: Westward 2
API #069-06103



Photo 5. Tank painted silver. Debris on location.



Photo 6. Open vault oily substance on water

Inspection Photos
Location Name: Westward 2
API #069-06103



Photo 7. Animal burrow in berm.



Photo 8. Unused separator at vertical heater treater

Inspection Photos
Location Name: Westward 2
API #069-06103



Photo 9. Gas sales riser on north side of treater shed. Valve in closed position



Photo 10. Stained soil in treater shed

Inspection Photos
Location Name: Westward 2
API #069-06103



Photo 11. Stained soil and abandoned unmarked uncapped 3" riser in treater shed . Seep in treater wall.



Photo 12. Gauge indicates no pressure on treater

Inspection Photos
Location Name: Westward 2
API #069-06103



Photo 13. Second seep in treater wall



Photo 14. No chart to indicate gas sales

Inspection Photos
Location Name: Westward 2
API #069-06103



**Photo 15. Vertical heater treater with insulation coming off.
Unused horizontal separator**



**Photo 16. Unmarked 2" poly line stubbed out on south side
of unused separator**

Inspection Photos
Location Name: Westward 2
API #069-06103



Photo 17. Looking NW at used separator, heater treater and poly line



Photo 18. Looking west at production tank. Note Hwy 287 in background

Inspection Photos
Location Name: Westward 2
API #069-06103



Photo 19. Looking south at wellhead



Photo 20. Looking west at wellhead. Note misc fittings at wellhead

Inspection Photos
Location Name: Westward 2
API #069-06103



Photo 21. Misc fittings at wellhead. Note closed flowline valve.



Photo 22. Unused gas volume pot to east of wellhead. Attempted to determine if discarded or plumbed in. Unable to move assume it is plumbed in

Inspection Photos
Location Name: Westward 2
API #069-06103



Photo 23. Misc debris in grass east on volume pot. Piping and rig anchors can be visualized.



Photo 24. Wellhead looking east. Fencing is not appropriate for livestock on site