



Photo 1: Facing northeast along the main access road. Installed gravel and crowned the driving surface to establish sheet flow.



Photo 2: Pulled gravel back onto the driving surface.



Photo 3: Facing south along the main road which goes through location. Pulled gravel back onto the driving surface.



Photo 4: Facing southwest toward the cut slope of the location. The rills were raked out, the sediment accumulation was removed and a dirt berm was installed at the toe of the cut slope.