

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2017

Submitted Date:

06/09/2017

Document Number:

685303265**FIELD INSPECTION FORM**
 Loc ID 320861 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 26625Name of Operator: ELM RIDGE EXPLORATION COMPANY LLCAddress: 12225 GREENVILLE AVE STE 950City: DALLAS State: TX Zip: 75243-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Redmond, Nolan	720-484-2347	Inspections@catamountep.com	All Inspections
Archuleta, Amy		aarchuleta@elmridge.net	SW Inspection Reports
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205259	WELL	PR	03/16/2000	GW	007-06137	PARGIN MOUNTAIN UNIT 9	PR

General Comment:[See link at end of report for path to downloadable pictures. Witnessed MIT 06/08/2017.](#)

Inspected FacilitiesFacility ID: 205259 Type: WELL API Number: 007-06137 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Production records indicate last reported production was July 2014. Inspection status reflects well as PR but electronic well production record shows well has been reported as SI since August 2014. MIT completed to comply with Rule 326.b.

Well was pressured up to initial test pressure of 420 psi. A leak was discovered at test connection as reflected on the chart. Connection was tightened and well pressured back up to 420 psi. Pressure was stable and 420 psi was maintained throughout the rest of the extended 30 minute test period. See attached photo documentation. Operator will submit required Form 21 and chart.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303284	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167468
685303285	Chart record of leak at connection.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167469
685303286	Chart 10 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167470
685303287	Chart 20 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167471
685303288	Chart 30 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167472
685303289	Completed chart.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167473