

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2017

Submitted Date:

06/09/2017

Document Number:

674104035

FIELD INSPECTION FORM

Loc ID 323610 Inspector Name: Wolfe, Stephen On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10548
Name of Operator: HRM RESOURCES II LLC
Address: 410 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Prohaska, April	303-893-6621	aprohaska@hrmres.com	All Inspections
Pape, Terry	303-893-6621	tpape@hrmres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245472	WELL	SI	02/01/2017	GW	123-13267	DECHANT 1-19	EG

General Comment:

[2017 Flowline NTO Inspection](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	corrective date
Flow Line		
Comment: IN USE: WELLHEAD- 1-2" steel riser, 1 well site. SEPARATOR- 4-2" steel risers. TANKS- 2-2" steel risers.		
Corrective Action:		Date: _____

Venting:

Yes/No		
Comment:		
Corrective Action:		Date: _____

Flaring:

Type	
Comment:	
Corrective Action:	Date: _____

Inspected Facilities

Facility ID: 245472 Type: WELL API Number: 123-13267 Status: SI Insp. Status: EG

Completion

Operation:
 Date Flowback:
 Contractor:
 Comment:
 Corrective Action: Date:

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: No Test Result: Pass Charted: No

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: 5/8/17 Flowline from wellhead to separator tested with 290 psi wellhead fluids for 30 min by ZD with HRM.

Corrective Action: Date:

#2	Type: Sales Line	of Lines
----	------------------	----------

Flowline Description

Flowline Type: Sales Line Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: No Test Result: Pass Charted: No

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: 5/8/17 Sales line from separator to gas sales meter tested with 105 psi gas for 30 min by ZD with HRM.

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674104037	Separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167561
674104038	Separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167562
674104249	Pressure test report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167563
674104250	Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167564
674104251	Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167565
674104252	Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167566