

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2017

Submitted Date:

06/06/2017

Document Number:

674104073**FIELD INSPECTION FORM**
 Loc ID 320436 Inspector Name: Wolfe, Stephen On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pape, Terry	970-768-5700	tpape@hrmres.com	
Prohaska, April	303-893-6621	aprohaska@hrmres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203753	WELL	PR	04/18/1995	OW	001-09313	HSR-CUNNINGHAM 7-10	EG

General Comment:[2017 Flowline NTO Inspection](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

#

Comment: IN USE: WELLHEAD- 2-2" steel risers, 1 well site and 1 bradenhead to surface, 1-1" steel risers, connected to wellhead. SEPARATOR- 2-2" steel risers, 2-1" risers, 1 to well and 1 to ECD. ECD- 1-1" steel supply line, 1-2" steel flowline.

Corrective Action: Date:

Type: Flow Line

#

Comment: NOT IN USE: SEPERATOR- 1-2" steel riser. ECD- 1-2" steel riser

Corrective Action: Date: **Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Inspected Facilities

Facility ID: 203753 Type: WELL API Number: 001-09313 Status: PR Insp. Status: EG

Flowline

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: Material:

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: No Test Result: Pass Charted: No

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: 5/6/17 Flowline from wellhead to separator tested with wellhead fluids to 115 psi for 30 mins by ZD with HRM.

Corrective Action: Date:

#2	Type: Sales Line	of Lines	
----	------------------	----------	--

Flowline Description

Flowline Type: Sales Line Size: Material:

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: No Test Result: Pass Charted: No

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: 5/6/17 Sales line from separator to gas sales meter tested with wellhead fluids to 105 psi for 30 mins by ZD with HRM.

Corrective Action: Date:

#3	Type: Process Piping	of Lines	
----	----------------------	----------	--

Flowline Description

Flowline Type: Process Piping Size: Material:

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: No Test Result: Pass Charted: No

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment**Comment:** 5/6/17 1" supply line from separator to wellhead tested with wellhead fluids to 88 psi for 30 mins by ZD with HRM.**Corrective Action:****Date:****Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674104193	Separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167586
674104194	Flowlines	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167587
674104195	ECD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167588
674104196	Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167589
674104197	Pressure test report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167590