

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2017

Submitted Date:

05/30/2017

Document Number:

681600041

FIELD INSPECTION FORM

Loc ID: 307120 Inspector Name: KOEHLER, BOB On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10312
 Name of Operator: PROSPECT ENERGY LLC
 Address: 1036 COUNTRY CLUB ESTATES DR
 City: CASTLE ROCK State: CO Zip: 80108

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Gracey, Cam	970-567-6871	graceyservices@msn.com	Foreman for Prospect Energy
Giltner, Ward		wgiltner@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216908	WELL	SI	10/27/2014	ERIW	069-06095	MSSU 30-7	EG

General Comment:

2017 Flowline NTO Inspection 1000' Buffer

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	Active 2" steel riser comes out of ground at back of shed (N), then heads toward wellhead (S) (40.636165, -105.04107) before going underground. Unused 2" steel riser beneath active line. Well plumbed to injection flowline via rubber (reinforced?) hose. Well actively injecting.		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	Capped-(not painted)-unused 2" steel flowline beneath active 2" flowline. See photo. Wellhead 40.636165, -105.04107		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 216908 Type: WELL API Number: 069-06095 Status: SI Insp. Status: EG**COGCC Comments**

Comment	User	Date
Operator needs to replace illegible sign, lost photo! Met operator representative in yard but operator did not accompany COGCC to wells. COGCC inspectors were Mike Leonard and Bob Koehler.	koehlerb	05/30/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401300790	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163086
681600042	Prospect Energy MSSU-30-7: View to NE, active 2" riser up and down, capped inactive 2", well w/hose	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163055