

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2017

Submitted Date:

06/02/2017

Document Number:

681600074**FIELD INSPECTION FORM**

Loc ID 437911 Inspector Name: KOEHLER, BOB On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10640Name of Operator: EWS 1 DJ BASIN LLCAddress: 43904 CR 105City: BRIGGS DALE State: CO Zip: 80611**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Goddard, Jim		jgoddard@expedition-water.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159480	UIC DISPOSAL	AC	11/14/2014	DSPW	-	EWS 1 UIC	EG
437909	WELL	IJ	11/14/2014	DSPW	123-39770	EWS 1	EG

General Comment:2017 Flowline NTO Inspection Statewide.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

2

Comment: Two 4" steel flow lines exit east side of pump house building near NE corner, one line each from 2 pumps inside. Lines merge immediately outside, single line then heads underground, and is connected to EWS-1 wellhead (40.63974, -104.06681). Lines exit building at 40.638926, -104.066973. Second unused 4" steel line at NE corner of pump house capped, to be used for EWS-1A if built (permit = 40.63977, -104.0602). Termination of 2nd line is underground, location unknown.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: <u>159480</u>	Type: <u>UIC</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EG</u>
Facility ID: <u>437909</u>	Type: <u>WELL</u>	API Number: <u>123-39770</u>	Status: <u>IJ</u>	Insp. Status: <u>EG</u>

COGCC Comments

Comment	User	Date
Operator Facility Manager conducted tour for COGCC inspector. One active 4" flowline and one unused 4" line.	koehlerb	06/02/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401300799	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163095
681600075	EWS-1 Facility Flow Line Exit Pump House	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163077
681600076	EWS-1 Wellhead and 4"-Steel Riser	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163078