



photo 1: Facing west toward the location. There is equipment that remains at the east side of the location.



photo 2: The pipe infrastructure has valve handles that have not been locked and tagged out.



photo 3: There is a tag on the pipe line which is faded and not readable.



photo 4: There valve is locked out however the tagged is faded and cannot be identified.



photo 5: Facing toward the pipe infrastructure. Lat/Long:39.98396,-104.64378



photo 6: Sign at the location.



photo 7: Center of the location facing west. The vegetation is establishing well at the western side of the location.



photo 8: Center of the location facing east. The vegetation has not established at the east side of the location and there are predominately undesirable weeds and noxious weeds.



photo 9: There are noxious weeds growing at the location (Canada thistle).



photo 10: The fence around the location is in disrepair. There are also noxious weeds shown in the photo (Common mullien).

Inspection Photos: API# 05-001-06729

Date: June 14, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources