

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: Followup to F-19 #450872 PW spill overflow from HDPE-lined steel SPCC. Spill overflowed to north into tilled dirt swale tertiary containment. Swale prevented discharge to Ryan Gulch. No signs of residual contamination. De minimus rainwater in SPCC has no sheen, staining or odor.

Corrective Action: Per F-19 COA: Assess nature and extent of contamination with confirmation soil samples. Remediate to Table 910-1 standards and provide documentation in a either a Supplemental F-19 if cleaned up immediately and/or F-27 if extended remediation such as landfarming contaminated soil is required. Landfarming must also be approved by surface owner. Documentation must include a figure showing spill area with sample locations plus laboratory results.

Date: 07/19/2017

Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674300906	Looking NE at tertiary swale and SPCC	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170829
674300907	SPCC w clear stormwater	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170830