

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2017

Submitted Date:

06/15/2017

Document Number:

674005369**FIELD INSPECTION FORM**

Loc ID 416983 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10312Name of Operator: PROSPECT ENERGY LLCAddress: 1036 COUNTRY CLUB ESTATES DRCity: CASTLE ROCK State: CO Zip: 80108**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                     | Comment |
|--------------|-------|---------------------------|---------|
| Twele, Megan |       | mtwele@progressivepcs.net |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 416981      | WELL | PR     | 06/01/2014  | OW         | 069-06399 | MARTINEZ 3    | PR          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |           |       |  |
|--------------------|-----------|-------|--|
| Type               | WELLHEAD  |       |  |
| Comment:           | Chainlink |       |  |
| Corrective Action: |           | Date: |  |

**Equipment:**

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| Type: Pump Jack    | # 1 |       | corrective date |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

**Tanks and Berms:**

| Contents           | #                             | Capacity | Type                | Tank ID | SE GPS |
|--------------------|-------------------------------|----------|---------------------|---------|--------|
|                    |                               |          | CENTRALIZED BATTERY |         | ,      |
| Comment:           | Shared with Martinez battery. |          |                     |         |        |
| Corrective Action: |                               |          |                     |         | Date:  |

**Paint**

|                  |                      |
|------------------|----------------------|
| Condition        | <input type="text"/> |
| Other (Content)  | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type)     | <input type="text"/> |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 416981 Type: WELL API Number: 069-06399 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**Flowline**

#1 Type: Well Site

of Lines

Flowline DescriptionFlowline Type: Well Site

Size:

Material:

Variance:

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure TestingWitnessed: YesTest Result: PassCharted: YesCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

Flow line pressure test.  
 Line is shared with API 05-069-05134  
 Segment tested between wellhead and Martinez battery.  
 Normal operating presesure: 80 PSI  
 Pressure at start of test: 100 PSI  
 Pressure at 5 minute interval: 97 PSI  
 Pressure at 10 minute interval: 96 PSI  
 Pressure at 15 minute interval: 95 PSI  
 Test performed by Mike Staabl and Miles Gracey

carlilec

06/15/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 674005370    | Photos      | <a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4171970">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4171970</a> |