

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2017

Submitted Date:

06/06/2017

Document Number:

674104067

**FIELD INSPECTION FORM**

Loc ID 320437 Inspector Name: Wolfe, Stephen On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10548  
Name of Operator: HRM RESOURCES II LLC  
Address: 410 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Pape, Terry	970-768-5700	tpape@hrmres.com	
Prohaska, April	303-893-6621	aprohaska@hrmres.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203754	WELL	PR	08/29/1995	GW	001-09314	HSR-LUNNON 2-3	EG

**General Comment:**

[2017 Flowline NTO Inspection](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Flow Line

#

corrective date

Comment: **IN USE: WELLHEAD- 2-2" steel risers, 1 wellsite and 1 surface casing. SEPARATOR- 3-2" steel risers. 1 wellsite, 1 bypass, 1 gas sales. PROCESS PIPING- 2-1" steel risers, connected from wellhead to separator. GAS SALES- 1-2" steel riser.**

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 203754 Type: WELL API Number: 001-09314 Status: PR Insp. Status: EG

**Flowline**

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: Material:  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: No Test Result: Pass Charted: No

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: 5/6/17 Flowline from wellhead to separator tested with wellhead fluids to 190 psi for 15 mins by ZD with HRM.

Corrective Action: Date:

#2	Type: Sales Line	of Lines
----	------------------	----------

Flowline Description

Flowline Type: Sales Line Size: Material: Carbon Steel  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: 5/6/17 Sales line from separator to gas sales meter tested with wellhead fluids to 100 psi for 30 mins by ZD with HRM.

Corrective Action: Date:

#3	Type: Process Piping	of Lines
----	----------------------	----------

Flowline Description

Flowline Type: Process Piping Size: Material:  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: No Test Result: Pass Charted: No

COGCC Rules(check all that apply)

1101. Installation and Reclamation     1102. Operations, Maintenance, and Repair     1103. Abandonment

Comment: 5/6/17 1" supply line from separator to wellhead tested with wellhead fluids to 135 psi for 15 mins by ZD with HRM.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401305323	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167614">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167614</a>
674104163	Wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167570">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167570</a>
674104164	Separator	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167571">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167571</a>
674104176	Pressure test report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167572">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167572</a>