

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2017

Submitted Date:

06/09/2017

Document Number:

678800247**FIELD INSPECTION FORM**
 Loc ID 451015 Inspector Name: LEONARD, MIKE On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING, INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Oil, Magpie		magpieoil@yahoo.com	
Burn, Diana		diana.burn@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451017	TANK BATTERY	AC	06/09/2017		-	Hein & Hart #1 Tank Battery	EG

**General Comment:**2017 Flowline NTO Inspection 1000' Buffer

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Containment device at loadline is full.		
Corrective Action:	Empty containment device to prevent spillage	Date:	06/16/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	GPS 40.37169/-105.05738		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	North of separator 4-3" , 1-2" , 1-1" plugged not marked or tagged. 2-2" with valves not tagged, marked or locked out. At separator 1-2" and 1-3" riser not tagged or marked. At SE corner of tank containment 1-3" plugged not marked or tagged. NTO Phase 1, Part 2: Any existing flowline or pipeline riser not in use must be clearly marked using fluorescent paint, have all operating valves removed and be capped (locked out/tagged out, bull plugged, or blind flange) until it can be cut-off below grade and sealed pursuant to Rule 1103 and the statewide Flowline NTO.		
Corrective Action:	Comply with Phase I-Part 2 of the May 2, 2107 Flowline NTO.	Date:	05/30/2017
Type: Flow Line	# 13		
Comment:	At separator & GMR (GPS 40.37169/-105.05738) 6-2" risers in use, 5-3" risers in use. At tank 1-33 and 1-2" in use.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		

Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.371430,-105.057310

Comment:	
Corrective Action:	Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT		40.371960,-105.057270

Comment:	
Corrective Action:	Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate

Comment:	Berms have worn down. Lid is ajar on vault overflow will result in spillage and potential escape from secondary containment
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1). Date: 07/08/2017

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 451017 Type: TANK API Number: - Status: AC Insp. Status: EG**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401305238	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167401">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167401</a>
678800248	Battery Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167379">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167379</a>