

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/09/2017

Submitted Date:

06/09/2017

Document Number:

678800251**FIELD INSPECTION FORM**

Loc ID 319085 Inspector Name: LEONARD, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING, INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email               | Comment |
|--------------|-------|---------------------|---------|
| Oil, Magpie  |       | magpieoil@yahoo.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 242857      | WELL | PR     | 05/18/1983  | OW         | 123-10648 | SCHRAGE 2     | EG          |

**General Comment:**2017 Flowline NTO Inspection 1000' Buffer

**Location**Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | Adequate |       |  |
| Corrective Action: |          | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Fencing/:**

|                    |            |       |  |
|--------------------|------------|-------|--|
| Type               | WELLHEAD   |       |  |
| Comment:           | steel pipe |       |  |
| Corrective Action: |            | Date: |  |

**Equipment:**

|                    |                                |       |                 |
|--------------------|--------------------------------|-------|-----------------|
| Type: Plunger Lift | #                              |       | corrective date |
| Comment:           |                                |       |                 |
| Corrective Action: |                                | Date: |                 |
| Type: Flow Line    | #                              |       |                 |
| Comment:           | 1-2" riser plumbed at wellhead |       |                 |
| Corrective Action: |                                | Date: |                 |

**Tanks and Berms:**

|                    |   |          |                     |         |        |
|--------------------|---|----------|---------------------|---------|--------|
| Contents           | #                                       | Capacity | Type                | Tank ID | SE GPS |
|                    |   |          | CENTRALIZED BATTERY |         | ,      |
| Comment:           | Centralized battery facility ID# 451018 |          |                     |         |        |
| Corrective Action: |   | Date:    |                     |         |        |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

|      |          |                     |                     |             |
|------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|      |          |                     |                     |             |



**Inspected Facilities**Facility ID: 242857 Type: WELL API Number: 123-10648 Status: PR Insp. Status: EG**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description             | URL   |
|--------------|-------------------------|---|
| 401305300    | INSPECTION<br>SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167524">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167524</a> |
| 678800252    | Wellhead                | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167520">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167520</a> |