

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/08/2017

Submitted Date:

06/09/2017

Document Number:

681700554

FIELD INSPECTION FORM

Loc ID 319759 Inspector Name: Arauza, Steven On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 95620
Name of Operator: WESTERN OPERATING COMPANY
Address: 1165 DELAWARE STREET #200
City: DENVER State: CO Zip: 80204

Findings:

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|----------------|----------------------------|------------------|
| Stapp, D. Scott | (303) 893-2432 | scott@westernoperating.com | |
| Reid, Marta | (303) 893-2438 | marta@westernoperating.com | Designated Agent |
| James, Steven D. | 303-893-2438 | steve@westernoperating.com | President |
| Axelson, John | | john.axelson@state.co.us | |
| Trujillo, Aaron | | aaron.trujillo@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 201274 | WELL | IJ | 10/15/2011 | DSPW | 001-06677 | DOWNING, RALPH 24-1 | EI |

General Comment:

COGCC followup Environmental Inspection of wellhead, former tank battery, and remediation/reclamation area (Remediation Project #5015). Operator has been required by several past field inspection reports (COGCC docs #200336714, #667500193, & #681700120) to provide updates to ongoing remediation project at former pit area north of tank battery. No updates have been received and Remediation Project #5015 is to remain open until the area passes final reclamation inspection. Fenced remediation/reclamation area contained primarily weeds on the date of this inspection. As a result, COGCC Area Reclamation Specialist has been included as a contact on this report.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | BATTERY | | |
| Comment: | Former tank battery area remains fenced, sign has been removed. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 07/09/2017 |
| Type | WELLHEAD | | |
| Comment: | Adequate. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: 07/09/2017

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | WEEDS | | |
| Comment: | Site-wide uncontrolled weeds, especially at former tank battery location and fenced remediation area. | | |
| Corrective Action: | Comply with Rule 603.f using the Rule 603.f guidance document for further details. | Date: | 06/19/2017 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 201274 Type: WELL API Number: 001-06677 Status: IJ Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [Per 4/7/2016 Field Inspection Report \(doc #681700120\): Additional maintenance is required at reclamation site. Operator must submit a Form 4 Sundry Notice to request a final reclamation inspection once the site is brought into compliance with 1000-Series rules. Remediation Project #5015 will remain open until reclamation site passes final reclamation inspection.](#)

Corrective Action: Remediation Project update has been required by multiple previous FIRs, but no updates have been received. Immediately provide written update of reclamation plan for fenced remediation area including required weed control and reseedling to COGCC EPS, per 6/7/2013 Inspection Report (doc #667500193).

Date: 07/31/2013

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 401305143 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167217 |
| 681700563 | Wellhead sign and shed. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167199 |
| 681700564 | Wellhead. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167200 |
| 681700565 | SE corner of former battery (looking NW). | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167201 |
| 681700566 | SW corner of former battery (looking NE). | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167202 |