

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2017

Submitted Date:

06/09/2017

Document Number:

685303263**FIELD INSPECTION FORM**Loc ID 320891 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 26625Name of Operator: ELM RIDGE EXPLORATION COMPANY LLCAddress: 12225 GREENVILLE AVE STE 950City: DALLAS State: TX Zip: 75243-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	SW Inspection Reports
Archuleta, Amy		aarchuleta@elmridge.net	SW Inspection Reports
Redmond, Nolan	720-484-2347	Inspections@catamountep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282169	WELL	SI	12/10/2014	GW	007-06220	TABOR 1	SI

General Comment:[See link at end of report for path to downloadable pictures. Witness MIT completed 06/08/2017.](#)

Inspected FacilitiesFacility ID: 282169 Type: WELL API Number: 007-06220 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Production records indicate last reported production was July 2014. Well has been reported as SI since August 2014. MIT completed to comply with Rule 326.b.

Well was pressured up to initial test pressure of 400 psi. Pressure was stable and 400 psi was maintained throughout extended 30 minute test period. See attached photo documentation. Operator will submit required Form 21 and chart.

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401305266	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167503
685303273	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167457
685303274	Chart 5 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167458
685303275	Chart 10 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167459
685303276	Chart 25 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167460
685303277	Completed chart.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167461