

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/08/2017

Submitted Date:

06/09/2017

Document Number:

685303265

### FIELD INSPECTION FORM

Loc ID 320861 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 26625  
 Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC  
 Address: 12225 GREENVILLE AVE STE 950  
 City: DALLAS State: TX Zip: 75243-

**Findings:**

- 5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	<a href="#">SW Inspection Reports</a>
Redmond, Nolan	720-484-2347	Inspections@catamountep.com	<a href="#">All Inspections</a>
Archuleta, Amy		aarchuleta@elmridge.net	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205259	WELL	PR	03/16/2000	GW	007-06137	PARGIN MOUNTAIN UNIT 9	PR

**General Comment:**

[See link at end of report for path to downloadable pictures. Witnessed MIT 06/08/2017.](#)

**Inspected Facilities**

Facility ID: 205259 Type: WELL API Number: 007-06137 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

**Comment:** Production records indicate last reported production was July 2014. Inspection status reflects well as PR but electronic well production record shows well has been reported as SI since August 2014. MIT completed to comply with Rule 326.b.

Well was pressured up to initial test pressure of 420 psi. A leak was discovered at test connection as reflected on the chart. Connection was tightened and well pressured back up to 420 psi. Pressure was stable and 420 psi was maintained throughout the rest of the extended 30 minute test period. See attached photo documentation. Operator will submit required Form 21 and chart.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401305268	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167505">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167505</a>
685303284	Wellhead sign.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167468">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167468</a>
685303285	Chart record of leak at connection.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167469">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167469</a>
685303286	Chart 10 min.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167470">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167470</a>
685303287	Chart 20 min.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167471">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167471</a>
685303288	Chart 30 min.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167472">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167472</a>
685303289	Completed chart.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167473">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167473</a>