

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2017

Submitted Date:

06/16/2017

Document Number:

674901712**FIELD INSPECTION FORM**Loc ID 313609 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46685Name of Operator: KINDER MORGAN CO2 CO LPAddress: 1001 LOUISIANA ST SUITE 1000City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Millican, Chris		chris_millican@kindermorgan.com	
Chesson, Bob		robert.chesson@state.co.us	
Conway, James	970-882-5505	james_conway@kindermorgan.com	<a href="#">SW Inspection Reports</a>
Swift, Barry	970-882-5545	barry_swift@kindermorgan.com	<a href="#">SW Inspection Reports</a>
Gintautas, Peter		peter.gintautas@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292924	WELL	PR	06/26/2008	GW	083-06633	GOODMAN POINT 9	EI

**General Comment:**

On June 13, 2017 COGCC SW EPS collected produced water samples from the Kinder Morgan Goodman Point #9 at the Goodman Point Central Processing Facility. Kinder Morgan representatives Mike Hannigan and Brad Mustoe were present during the collection of water samples for the COGCC 2017 NORM Produced Water Study. Kinder Morgan collected split samples.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:  Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	292924	Type:	WELL	API Number:	083-06633	Status:	PR	Insp. Status:	EI

--

**Environmental****Spills/Releases:**

Type of Spill:	Estimated Spill Volume:
Comment:	
Corrective Action:	Date:
Reportable:	GPS: Lat Long
Proximity to Surface Water:	Depth to Ground Water:

**Water Well Complaint:**

DWR Receipt Num:	Owner Name:	GPS :	Lat	Long
------------------	-------------	-------	-----	------

**Field Parameters:**

Sample Location:	Other	Comment:	Separator
<b>Sample</b>	Sample Type:	PRODUCED	
Time:	06/13/2017 09:30 (MM/dd/yyyy hh:mm)	GPS: Lat	37.405524 Long -108.792959
BTEX:	TPH:	Anion:	Captions: General Chemistry:
Dissolved Methane:	Composition:	Stable Isotopes:	8260:
8270:	RCRA Metals:	910-Metals:	PAH:
Other:	2017 COGCC NORM Produced Water Study		
Comment:	Samples collected from test separator within Goodman Point CPF.		

**Lab:**

Lab Name
ALS

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On June 13, 2017 COGCC SW EPS Jim Hughes collected produced water samples from the Kinder Morgan Goodman Point #9 at the Goodman Point Central Processing Facility. Kinder Morgan representatives Mike Hannigan and Brad Mustoe were present during the collection of water samples for the COGCC 2017 NORM Produced Water Study. Kinder Morgan collected split samples.</p> <p>A sample port was prepared by Kinder Morgan on piping from a test separator where produced water from the GP #9 well was isolated. Split samples were collected from ¼" stainless steel tubing. Samples were shipped to ALS for analysis.</p>	hughesj	06/16/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901713	Sample port configuration.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172847">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172847</a>
674901714	Sample port location on test separator.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172848">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172848</a>
674901715	Cubitainer sample collection.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172849">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172849</a>