

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/16/2017

Submitted Date:

06/16/2017

Document Number:

670201508**FIELD INSPECTION FORM**

Loc ID 450650 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num: _____

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 99999
 Name of Operator: OLD OPERATORS - STATUS UNKNOWN
 Address: SEE COMMENT LINE IN WELL
 City: XXXXXXX State: XX Zip: _____

Findings:

- 2 Number of Comments
1 Number of Corrective Actions
☒ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ellsworth, Stuart		stuart.ellsworth@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450647	WELL	TA	05/17/2017	GW	077-10381	DB Orphan 8	TA

General Comment:

Orphan well plugging project #PO PHAA 2017*12735. Contractor is RACS LLC.

Inspected FacilitiesFacility ID: 450647 Type: WELL API Number: 077-10381 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: On location to observe well after placement of 25 gallons of WellLock Resin on 6/14/2017. Tagged resin top at 8'1" below top of casing. Top was at 10' on 6/14 before placement. About 20 gallons of resin went into voids and 5 gallons to raise the top to 8'1". Measured methane (LEL) at 22% in casing. Placed 5 gallons of water in casing at 9:30. Gas bubbling through the water was observed. Bubbling was intermittent and at times the water was still.

Corrective Action: Plug and abandon. Date: 06/23/2017