

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401311350
Date Received:
06/16/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 76840
Name of Operator: SCHNEIDER ENERGY SERVICES INC
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Jeff Schneider</u>	<u>970-867-9437</u>	<u>jeff@schneiderenergy.com</u>
<u>Kevin Bothwell</u>	<u>970-867-9437</u>	<u>kbothwell@schneiderenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 673504474
Inspection Date: 06/15/2017 FIR Submit Date: 06/16/2017 FIR Status: _____

Inspected Operator Information:

Company Name: SCHNEIDER ENERGY SERVICES INC Company Number: 76840
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 376152

Location Name: CHAMPLIN-62S63W Number: 35SWNE County: ADAMS
Qtrqtr: SWNE Sec: 35 Twp: 2S Range: 63W Meridian: 6
Latitude: 39.834200 Longitude: -104.402290

FACILITY - API Number: 05-001- -00 Facility ID: 201952

Facility Name: CHAMPLIN Number: 1-35
Qtrqtr: SWNE Sec: 35 Twp: 2S Range: 63W Meridian: 6
Latitude: 39.834200 Longitude: -104.402290

CORRECTIVE ACTIONS:

1 CA# 82054

Corrective Action: All Risers/ Flowlines/ Pipelines must abide by the Phase I of the May 2, 2017 Flowline NTO. Respond when corrective action is complete with date completed and photos attached to an FIRR response to CA. Make sure to identify both endpoints of all Risers/ Flowlines/ Pipelines. Date: 05/31/2017

Response: CA COMPLETED Date of Completion: 06/16/2017

Operator Comment: Dug up what appeared to be a riser and found to be just fitted buried approx 1' deep. The fittings were removed and the hole was backfilled. See Attached pictures

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 82055

Corrective Action: All Risers/ Flowlines/ Pipelines must abide by the phase II of the May 2, 2017 Flowline NTO. Respond when corrective action is complete with date completed and photos attached to an FIRR response to CA. Make sure to identify both endpoints of all riser Risers/ Flowlines/ Pipelines .

Date: 06/30/2017

Response: CA COMPLETED

Date of Completion: 06/16/2017

Operator Comment: Dug up what appeared to be a polly pipe rise that turned out to be a 1' piece of poly pipe stuck in the ground. The poly was removed. See Attached photo of the piece that was removed.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: We dug up and removed what appeared to be a riser but turned out to be some junk fittings and a 1' piece if 2" polly pipe and the hole was backfilled.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff Schneider

Signed: _____

Title: `President

Date: 6/16/2017 4:13:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401311363	Champlin 1-35 Junk Fittings
401311364	Champlin 1-35 Junk Fittings and Hole
401311366	Champlin 1-35 Junk Fitting in truck
401311367	Champlin 1-35 hole back filled.
401311376	Champlin 1-35 Picture of Ploy and fittings.

Total Attach: 5 Files