

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2017

Submitted Date:

06/17/2017

Document Number:

685303337**FIELD INSPECTION FORM**Loc ID 333532 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96705Name of Operator: WPX ENERGY PRODUCTION LLCAddress: P O BOX 3102 MS-25-2City: TULSA State: OK Zip: 74101**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|---|--|
| Inspection, WPX | 970-263-2716 | COGCCInspectionReportsSanJuan@wpxenergy.com | WPX Inspection Mailbox |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 213993 | WELL | PR | 07/03/1962 | GW | 067-05276 | TIFFANY 1 | PR |

General Comment:[2017 Flowline NTO Inspection Statewide](#)[See link at end of report for path to downloadable pictures. Inspection report contains corrective action and comment. See Good Housekeeping section of report for additional details.](#)

| Location | | | |
|--|---|-------------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt and gravel two track road. | | |
| Corrective Action | L | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Metal sign at gas meter run. | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign at produced water tank. | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | Operator contact information posted on wellhead sign. | | Date: _____ |
| Corrective Action: | | | |
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Dried weed debris trapped in fencing and corner of location behind produced water tank. | | |
| Corrective Action: | Remove debris to comply with Rule 603.f using Rule 603.f guidance document for further details. | | Date: 07/12/2017 |
| Type | OTHER | | |
| Comment: | Stained soil at muffler, wellhead, separator, and base of tank. | | |
| Corrective Action: | Clean up and remediate stained soil and gravel to comply with Rule 906.a. | | Date: 07/12/2017 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: _____ | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Steel post and hog wire fencing. | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Ancillary equipment | | # 1 | corrective date |
| Comment: | | Wellhead. | |
| Corrective Action: | | Date: | |
| Type: Other | | # 2 | |
| Comment: | | Sound wall. | |

| | | | |
|-----------------------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | In use - 2" steel line from wellhead tubing to separator inlet. All points on location. 37.07241/-107.57388 from scout card. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Telemetry equipment. | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | In use - 2" steel line from wellhead casing to compressor and separator. | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Compressor | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|----------|---------|--------|
| PRODUCED WATER | 1 | OTHER | Open Top | | , |
| Comment: | Open top tank with expanded metal cover and earthen berms. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 20 BBLS |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------|----|--|
| Yes/No | NO | |
|--------|----|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | | |
|-----------------------------|--|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 213993 | Type: WELL | API Number: 067-05276 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | PR - Review of electronic well file reflects last reported production as March 2017. | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: OTHER, RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: OTHER, RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|-----------------------------------|
| Berms | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | Berms around produced water tank. |
| Compaction | Pass | Gravel | Pass | | | |
| Gravel | Pass | | | | | |

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------------------------|---|
| 685303365 | Wellhead sign. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173685 |
| 685303366 | Stained soil at muffler. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173686 |
| 685303367 | Stained soil at wellhead. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173687 |
| 685303368 | Stained soil at separator. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173688 |
| 685303369 | Stained soil at base of tank. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173689 |
| 685303370 | Debris in fence and backside of tank. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173690 |