Inspector Name: BURGER, CRAIG

FORM INSP

X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DB Orphan 8

Inspection Date:

06/06/2017
Submitted Date:

06/08/2017
Document Number:

670201499

TA

# FIELD INSPECTION FORM

Loc ID	Inspector Name:		On-Site I	On-Site Inspection		Status Summary:		
450650	BURGER, CRAIG		2A	2A Doc Num:		THIS IS A FOLLOW UP INSPECTION		
Operator Information:  OGCC Operator Number: 99999						FOLLOW UP INSPECTION REQUIRED  NO FOLLOW UP INSPECTION REQUIRED		
OGCC Operator Number:99999  Name of Operator: OLD OPERATORS - STATUS UNKNOWN						Findings:		
Address: SEE COMMENT LINE IN WELL						2 Number of Comments 1 Number of Corrective Actions		
City:	XXXXXXX	State:	XX	Zip:		Corrective Action Response Requested		
Contact Inf	ormation:				•			
Contact Name Pho		Phon	е	Email		Comment		
Andrews, Dave			david.andrews@state.co.us					
Inspected F	acilities:							
Facility ID	Туре	Status	Status Date	Well Class	API Num	Facility Name Insp	Status	

077-10381

GW

### **General Comment:**

WELL

450647

Orphan well plugging project #PO PHAA 2017\*12735. Contractor is RACS LLC.

05/17/2017

TΑ

Inspector Name: BURGER, CRAIG

#### **Inspected Facilities** Facility ID: 450647 WELL API Number: 077-10381 Status: TA Insp. Status: TA Type: **Workover** Comment: 7:30. Ran camera to 35'. No visibility due to gas bubbles. 8:30 ran impression block. Stacked out and got no impression. Rigged up to wash down and retry. 9:00 washing down with washover pipe. 10:00 ran impression block. Looks like no more fish in hole. Measured flow out of 2" with garbage bag about 40 gal in 20 min. 12:45 reaming out with 6 3/4" drill bit. Shut down 13:30 to 14:00 due to power swivel issue. 14:45 remaing at 33'. 15:45 drilling formation at 60', slight rate increase.

Corrective Action: Plug and abandon.

17:30 off location.

06/09/2017 Date:

## **Attached Documents**

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

17:00 drilled to TD from ground surface of 90.9'.

Document Nun	n Description	URL
401306479	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168726