

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2017

Submitted Date:

06/12/2017

Document Number:

685200326**FIELD INSPECTION FORM**
 Loc ID 326291 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|----------------------------|---------------------------------|
| Woolley, Jeff | | jeff_woolley@xtoenergy.com | SJB inspections |
| Woolley, Jeff | | jeff_woolley@xtoenergy.com | SJB inspections |
| Hixon, Logan | | logan_hixon@xtoenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 216181 | WELL | PR | 10/10/1991 | GW | 067-07787 | SE DURANGO-WRIDE 6-1 | PR |

General Comment:[2017 Flowline NTO Inspection 1000' Buffer](#)[Shadowing Operator Pressure Testing Team](#)

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | Date: _____ |
| Corrective Action: | | |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|--------------------|---|-------|-----------------|
| | | | corrective date |
| Type: Flow Line | # 1 | | |
| Comment: | 2", wellhead to sep, both points on location, coordinates 37.241876/-107.781086 from scout card | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | 1" supply gas, both points on location, 37.241876/-107.781086 from scout card | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 216181 Type: WELL API Number: 067-07787 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Flowline

#1 Type: Well Site

1 of Lines

Flowline DescriptionFlowline Type: Well SiteSize: 2"Material: Carbon Steel

Variance:

Age:

Contents: Natural GasIntegrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure TestingWitnessed: YesTest Result: PassCharted: YesCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: Both points are on location coordinates 37.241876/-107.781086 from scout card65.3-65.4 psig over 15 minute test w/ crystal gauge

Corrective Action:

Date:

#2 Type: Process Piping

1 of Lines

Flowline DescriptionFlowline Type: Process PipingSize: OtherMaterial: Carbon Steel

Variance:

Age:

Contents: Natural GasIntegrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure TestingWitnessed: YesTest Result: PassCharted: YesCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: both points on location coordinates 37.241876/-107.781086 from scout card40.1-39.6 psig using well gas, 15 minute test with crystal gauge

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401306362 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168524 |