

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2017

Submitted Date:

06/19/2017

Document Number:

674603382**FIELD INSPECTION FORM**

Loc ID 319664 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pape, Terry	303-893-6621	tpape@hrmres.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Prohaska, April	303-893-6621	aprohaska@hrmres.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200774	WELL	SI	03/01/2017	GW	001-06177	RANDALL 41-10	EG

**General Comment:**

2017 Flowline NTO Inspection 1000' Buffer; Witnessing removal of flowline risers and out of service flowline abandonments.

**Inspected Facilities**Facility ID: 200774 Type: WELL API Number: 001-06177 Status: SI Insp. Status: EG**Flowline**

#1	Type:	of Lines	
<u>Flowline Description</u>			
Flowline Type:	Size:	Material: <u>Carbon Steel</u>	
Variance:	Age:	Contents:	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:	Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
Comment:	HRM contractor (Shorty's) in process of removing unused flowline risers (previously identified and marked with fluorescent paint) and abandoning short sections of unused process piping flowlines at the Randall 41-10 and 32-10 facility/ battery; per COGCC Flowline NTO.		
Corrective Action:			Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674603389	Battery and signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174021">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174021</a>
674603390	Unused risers being removed near treater	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174023">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174023</a>
674603392	Unused risers removed per NTO	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174024">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174024</a>