

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2017

Submitted Date:

06/19/2017

Document Number:

674901743**FIELD INSPECTION FORM**Loc ID 322129 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46685Name of Operator: KINDER MORGAN CO2 CO LPAddress: 1001 LOUISIANA ST SUITE 1000City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Swift, Barry	970-882-5545	barry_swift@kindermorgan.com	SW Inspection Reports
Conway, James	970-882-5505	james_conway@kindermorgan.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Millican, Chris	970-882-5504	chris_millican@kindermorgan.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292053	WELL	PR	01/31/2017	STRT	033-06133	DOE CANYON 3	EI

General Comment:

On June 6, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan Doe Canyon #3. For the most recent field inspection report for this facility, please refer to document #200255764. Kinder Morgan representatives Mike Hannigan and Rick Gerst were on site during this inspection.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Rip Rap	Pass					
Waddles	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On June 6, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan Doe Canyon #3. For the most recent field inspection report for this facility, please refer to document #200255764. Kinder Morgan representatives Mike Hannigan and Rick Gerst were on site during this inspection. During this field inspection A+ well services was on location testing the well.	hughesj	06/19/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901744	DC #3 stormwater BMPs.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174851
674901745	A+ Well Services testing well.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174852