

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2017

Submitted Date:

06/20/2017

Document Number:

674901750**FIELD INSPECTION FORM**

Loc ID 417386 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 5  
 Name of Operator: COLORADO OIL & GAS CONSERVATION  
 Address: 1120 LINCOLN ST SUITE 801  
 City: DENVER State: CO Zip: 80203

**Findings:**

- 7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417389	WELL	AC	06/10/2015	GW	007-06293	DEEP CANYON MW 34-4-32-1	EI

**General Comment:**

On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Deep Canyon MW 34-4-32 #1. For the most recent field inspection report of this facility, please refer to document #674901156. The purpose of this site visit was to replace the desiccants, which was last completed on 6/9/16.

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:	Sign mounted to stock panel enclosure.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Sign mounted to stock panel enclosure.		
Corrective Action:		Date:	_____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
Comment:	Stock panel enclosure		
Corrective Action:		Date:	

**Equipment:**

		# 1			corrective date
Type: Ancillary equipment					
Comment:	In-Situ data logger				
Corrective Action:				Date:	
Type: Ancillary equipment		# 1			
Comment:	Telemetry				
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 417389 Type: WELL API Number: 007-06293 Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Deep Canyon MW 34-4-32 #1. For the most recent field inspection report of this facility, please refer to document #674901156. The purpose of this site visit was to replace the desiccants, which was last completed on 6/9/16. During this inspection the eight desiccant packets and the Desi-Tube were replaced. The three lead acid batteries were in good condition with no signs of corrosion.	hughesj	06/20/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901751	Deep Canyon MW 34-4-32 #1 location photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174856">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174856</a>
674901752	Deep Canyon MW 34-4-32 #1 equipment enclosures.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174857">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174857</a>