

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2017

Submitted Date:

06/20/2017

Document Number:

674901756

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
333983 _____ Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: _____ 5 _____
Name of Operator: COLORADO OIL & GAS CONSERVATION _____
Address: 1120 LINCOLN ST SUITE 801 _____
City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80203 _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 _____ Number of Comments
0 _____ Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298285	WELL	SI	06/15/2015	OBW	007-06264	FOSSET GULCH MW 34-5-14 1	EI
298286	WELL	SI	06/15/2015	OBW	007-06265	FOSSET GULCH MW 34-5-14 2	EI

General Comment:

On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Fosset Gulch MW 34-5-14 #1 and #2. For the most recent field inspection report of this facility, please refer to document #674901162. The purpose of this site visit was to replace the desiccants within the equipment enclosures.

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Location signs mounted to protective barricades surrounding well heads. Township in well name is incorrect. Legal description on sign is accurate.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Sign mounted to protective barricade surrounding ancillary equipment.		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel pipe protective barricade fencing surrounding well heads and ancillary equipment.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	In-Situ data logger.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry.		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 298285 Type: WELL API Number: 007-06264 Status: SI Insp. Status: EI

Facility ID: 298286 Type: WELL API Number: 007-06265 Status: SI Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Fosset Gulch MW 34-5-14 #1 and #2. For the most recent field inspection report of this facility, please refer to document #674901162. The purpose of this site visit was to replace the desiccants within the equipment enclosures. During this inspection all eight desiccant packets and the Desi-tube were replaced. This was last performed on 6/9/16. All battery terminals were in good condition with no signs of corrosion.</p>	hughesj	06/20/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901757	Incorrect well name on location sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174860
674901758	Fosset Gulch MW 34-5-14 location photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174861