

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2017

Submitted Date:

06/19/2017

Document Number:

682402254**FIELD INSPECTION FORM**
 Loc ID 322192 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	
		jbcrog@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209641	WELL	PR	12/01/2010	GW	039-06546	COGGINS 10-16	RI

**General Comment:**This is a stormwater inspection.

Inspected Facilities									
Facility ID:	209641	Type:	WELL	API Number:	039-06546	Status:	PR	Insp. Status:	RI

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Hydro Mulch	Pass					Temporary BMP

Comment: Operator shall implement long-term stabilization along the previously vegetated areas inside the guy line anchors that were sprayed to manage for weeds. It would be recommended by COGCC staff and the surface owner to stabilize all areas not needed for production with long-term, self sustaining vegetative stabilization. Currently, hydromulch is serving as a temporary stabilization BMP but additional long-term stabilization BMP(s) will need to be implemented. Please refer to the attached inspection photos.

Corrective Action:

Date: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
It should be noted the Operator did seed and hydromulch the areas inside the guy line anchors. However, very little germination was observed which might be affected by the residual chemical weed spray that was used in February 2017.	binschusc	06/19/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682402255	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174871">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174871</a>