

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2017

Submitted Date:

06/19/2017

Document Number:

685303390

FIELD INSPECTION FORM

Loc ID 333036 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: PO BOX 6501
City: ENGLEWOOD State: CO Zip: 80155

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Hixon, Logan	505-386-8018	logan_hixon@xtoenergy.com	SW EHS Tech
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	SW Inspection Reports
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214789	WELL	PR	10/23/2003	GW	067-06393	MCDONALD C 1	PR

General Comment:

[2017 Flowline NTO Inspection 1000' Buffer](#)
[Shadowing Operator Pressure Testing Team](#)
[Retest of Fruitland Coal wellhead tubing to separator inlet.](#)

Inspected Facilities

Facility ID: 214789 Type: WELL API Number: 067-06393 Status: PR Insp. Status: PR

Flowline

#1	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 3" Material: Carbon Steel
 Variance: Age: Contents: Natural Gas

Integrity Summary

Failures: Spills: Repairs Made: Yes
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Witnessed retest of flow line pressure test on steel gas line from wellhead Fruitland Coal tubing to separator inlet. Operator completed repairs replacing two baylon vaves on wellhead tree. All points are on location. 37.02751/-107.54599 from Scout Card. Testing was part of requirement of May 2, 2017 NTO. Test was conducted using Crystal gauge for pressure reading and charting. Starting pressure was 59.8 psi and ending pressure was 60.1 psi. Test duration was 15 minutes.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303393	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174872