

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/19/2017

Submitted Date:

06/20/2017

Document Number:

679700529**FIELD INSPECTION FORM**
 Loc ID 333069 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, COGCC		COGCCInspections@extracti onog.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245403	WELL	PR	02/01/2017	GW	123-13198	WINTER 15-19	EI
448567	TANK BATTERY	AC			-	Winters Battery	EI

General Comment:

COGCC Environmental Staff Inspection, Extraction is abandoning the Winter 10,15-19 tank battery and preparing site for abandonment. See inspection #679700530 for Tigges Winter 15-19-0 inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: [Sign present at tank battery](#)

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

1

Comment: [Gas meter present on location at 40.46470,-104.59097](#)

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment: [Separator is disconnected. Field crew on location abandoning tank battery.](#)

Corrective Action:

Date:

Type: Flow Line

#

Comment: [Field crew is onsite dismantling production equipment. Wellhead and separation equipment have been disconnected from flowlines. Flowlines must be abandoned per Rule 1103 and the Flowline Guidance Document.](#)

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	BV CONCRETE		,

Comment: [Field crew is preparing site for abandonment. Partially buried vessel is adjacent the Tigges 15-19-0 tank battery. Abandonment of a buried produced water vessel requires the Operator to submit a Form 27 per Rule 905.b.](#)

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:								Date:		
Contents		#	Capacity	Type		Tank ID	SE GPS			

CRUDE OIL	2	300 BBLS	STEEL AST		
Comment:	Field crew is present on location, emptying tanks and preparing site for abandonment and reclamation. Tanks are adjacent the Tigges Winter 15-19-0 tank battery				
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 245403 Type: WELL API Number: 123-13198 Status: PR Insp. Status: EIFacility ID: 448567 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700535	Extraction buried produced water vessel	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175105
679700536	Separator and meter shed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175106
679700537	Wellhead disconnected from flowlines	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175107