

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401308700  
Date Received:  
06/14/2017

## FIR RESOLUTION FORM

### CA Summary:

2 of 3 CAs from the FIR responded to on this Form

0 CA Completed  
2 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
<u>Jeff Rickard</u>	<u>720 737-5144</u>	<u>jrickard@extractionog.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 673504459  
Inspection Date: 06/14/2017 FIR Submit Date: 06/14/2017 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: EXTRACTION OIL & GAS LLC Company Number: 10459  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 320101

Location Name: WARREN-61S65W Number: 2SWSW County: ADAMS  
Qtrqr: SWS Sec: 2 Twp: 1S Range: 65W Meridian: 6  
W  
Latitude: 39.989440 Longitude: -104.637060

### FACILITY - API Number: 05-001- -00 Facility ID: 202622

Facility Name: WARREN Number: 1-2  
Qtrqr: SWS Sec: 2 Twp: 1S Range: 65W Meridian: 6  
W  
Latitude: 39.989440 Longitude: -104.637060

### CORRECTIVE ACTIONS:

1 ☒ CA# 81765

Corrective Action: All Risers/ Flowlines/ Pipelines must abide by the phase II of the May 2, 2017 Flowline NTO. Respond when corrective action is complete with date completed and photos attached to an FIRR response to CA. Make sure to identify both endpoints of all riser Risers/ Flowlines/ Pipelines .

Date: 06/30/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

The riser in question not a flowline under the definition in the 100 series rules, nor is it under Extractions control, it

Operator Comment: is owned by a gathering company, presumably Kerr McGee Gathering. From the photos provided, it appears the riser is plumbed to be a monitoring station and a methanol drip point for the gathering line.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor:

Staff, has reviewed the subject risers. It appears that this riser was in place specifically for the subject well that is now PA and therefore has no function. Per the reclamation rules 1004 (a) this riser is the responsibility of the Well Operator to remove or coordinate the removal. Until the riser is removed the location will not pass final reclamation and is out of compliance. The location has been out of compliance with the reclamation rules since 2010 and is covered with noxious weeds.

2  CA# 81766

Corrective Action: All Risers/ Flowlines/ Pipelines must abide by the Phase I of the May 2, 2017 Flowline NTO. Respond when corrective action is complete with date completed and photos attached to an FIR response to CA. Make sure to identify both endpoints of all Risers/ Flowlines/ Pipelines.

Date: 05/31/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator Comment: The riser in question not a flowline under the definition in the 100 series rules, nor is it under Extractions control, it is owned by a gathering company, presumably Kerr McGee Gathering. From the photos provided, it appears the riser is plumbed to be a monitoring station and a methanol drip point for the gathering line.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor:

Staff, has reviewed the subject risers. It appears that this riser was in place specifically for the subject well that is now PA and therefore has no function. Per the reclamation rules 1004 (a) this riser is the responsibility of the Well Operator to remove or coordinate the removal. Until the riser is removed the location will not pass final reclamation and is out of compliance. The location has been out of compliance with the reclamation rules since 2010 and is covered with noxious weeds.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff Rickard

Signed: \_\_\_\_\_

Title: Regulatory Compliance Co

Date: 6/14/2017 2:15:48 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401308700	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files