

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2017

Submitted Date:

06/20/2017

Document Number:

674901764**FIELD INSPECTION FORM**
 Loc ID 334385 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 5Name of Operator: COLORADO OIL & GAS CONSERVATIONAddress: 1120 LINCOLN ST SUITE 801City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267693	WELL	AC	06/15/2015	OBW	067-08802	MONITOR WELL 35-6-17-1	EI
267867	WELL	AC	06/15/2015	OBW	067-08814	MONITOR WELL 35-6-17-2	EI

General Comment:

On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Beaver Creek Ranch MW 35 -6-17 #1 and #2. For the most recent field inspection report for this facility, please refer to document #674901228. The purpose of this site visit was to replace desiccants in the equipment enclosures and troubleshoot the telemetry system.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign mounted to angle iron and expanded metal protective cages.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Sign mounted to metal shack housing ancillary equipment.	Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	4' x 4' x 4' expanded metal and angle iron protective cages surrounding well heads.		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	In-Situ data logger.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>267693</u>	Type:	<u>WELL</u>	API Number:	<u>067-08802</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>267867</u>	Type:	<u>WELL</u>	API Number:	<u>067-08814</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On June 12, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Beaver Creek Ranch MW 35-6-17 #1 and #2. For the most recent field inspection report for this facility, please refer to document #674901228. The purpose of this site visit was to replace desiccants in the equipment enclosures and troubleshoot the telemetry system.</p> <p>During this inspection eight desiccant packets and one Desi-tube were replaced. This was last completed on 5/23/16.</p> <p>This station had stopped reporting data. Upon further investigation, one of the fuses in the TL 201 enclosure had blown. The right fuse in this equipment enclosure was replaced and was functioning properly.</p> <p>All of the three batteries at this site were at 13.76 V.</p>	hughesj	06/20/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901765	Beaver Creek Ranch TL 201 enclosure.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175205
674901766	TL 201 enclosure w/ new fuse and desiccants.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175206