

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2017

Submitted Date:

06/20/2017

Document Number:

666803253

FIELD INSPECTION FORM

Loc ID 335534 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
Name of Operator: URSA OPERATING COMPANY LLC
Address: 1600 BROADWAY ST STE 2600
City: DENVER State: CO Zip: 80202

Findings:

- 16 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284083	WELL	PR	11/21/2009	GW	045-12083	VALLEY FARMS D1	PR
284084	WELL	SI	07/09/2015	DSPW	045-12082	VALLEY FARMS D3	PR
288635	WELL	PR	06/25/2013	GW	045-13298	VALLEY FARMS D10	PR
290434	WELL	PR	06/25/2013	GW	045-14109	VALLEY FARMS D13	PR

General Comment:

[2017 Flowline NTO Inspection 1000' Buffer](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Emission Control Device	# 1	Comment: 39.531147/-107.652562	Corrective Action:	Date:	
Type: Other	# 1	Comment: injection pump house, 39.531004/-107.653164	Corrective Action:	Date:	
Type: Horizontal Heated Separator	# 1	Comment: 39.530457/-107.652755	Corrective Action:	Date:	
Type: Plunger Lift	# 3	Comment: 39.531162/-107.653314	Corrective Action:	Date:	
Type: Ancillary equipment	# 1	Comment: Chemical unit at wellhead	Corrective Action:	Date:	
Type: Flow Line	#	Comment: Not in use 4-3", 1-1" 1-2", Marked with paint, see photo	Corrective Action:	Date:	
Type: Flow Line	#	Comment: In use; 3-2", 1-3" steel risers at wellhead, 12-2", 10-3", 2-1" risers at separators, 5-3", 2-1", 1-4" risers at tanks, 1-4", 1-3" pump house, 1-1" gas feed to ECB	Corrective Action:	Date:	
Type: Horizontal Heated Separator	# 4	Comment: 39.531053/-107.652614	Corrective Action:	Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,

Comment:		In same berm as condensate tank				Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	1	300 BBLs	STEEL AST		39.531236,-107.652264		
Comment:						Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	300 BBLs	STEEL AST				
Comment:		In same berm as 1 condensate tank				Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:						Date:	
Corrective Action:						Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	6	300 BBLs	STEEL AST		39.531050,-107.652938		
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities									
Facility ID:	<u>284083</u>	Type:	<u>WELL</u>	API Number:	<u>045-12083</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:								Date:	
Facility ID:	<u>284084</u>	Type:	<u>WELL</u>	API Number:	<u>045-12082</u>	Status:	<u>SI</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:								Date:	
Facility ID:	<u>288635</u>	Type:	<u>WELL</u>	API Number:	<u>045-13298</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:								Date:	
Facility ID:	<u>290434</u>	Type:	<u>WELL</u>	API Number:	<u>045-14109</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:								Date:	

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Culverts	Pass			
Gravel	Pass					
Berms	Pass					
		Ditches	Pass			
Culverts	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803254	URSA NTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175591
666803255	URSA NTO 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175592
666803256	URSA NTO 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175593