

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2017

Submitted Date:

06/20/2017

Document Number:

666803257**FIELD INSPECTION FORM**

Loc ID 335542 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288407	WELL	PR	06/25/2013	GW	045-13227	VALLEY FARMS E5	PR
288408	WELL	PR	03/24/2010	GW	045-13226	VALLEY FARMS E6	PR
288411	WELL	PR	01/22/2010	GW	045-13223	VALLEY FARMS E9	PR
288412	WELL	PR	10/08/2013	GW	045-13222	VALLEY FARMS E10	PR
288413	WELL	PR	01/05/2010	GW	045-13221	VALLEY FARMS E11	PR

General Comment:[2017 Flowline NTO Inspection 1000' Buffer](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

#

Comment: In use; 5-2" steel risers at wellhead, 26-2", 4-3", 1-1" risers at separators, 2-3", 1-1" risers at tanks, 1-1" gas feed to ECB

Corrective Action:

Date:

Type: Flow Line

#

Comment: Not in use 3-3", Marked with paint, see photo

Corrective Action:

Date:

Type: Emission Control Device

1

Comment: 39.528625/-107.646050

Corrective Action:

Date:

Type: Horizontal Heated Separator

8

Comment: 39.528755/-107.646016

Corrective Action:

Date:

Type: Plunger Lift

5

Comment: 39.528958/-107.646271

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		39.528835,-107.645941
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Murray, Richard

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLs	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 288407 Type: WELL API Number: 045-13227 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 288408 Type: WELL API Number: 045-13226 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 288411 Type: WELL API Number: 045-13223 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 288412 Type: WELL API Number: 045-13222 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 288413 Type: WELL API Number: 045-13221 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Gravel	Pass					
Berms	Pass					
		Culverts	Pass			
		Ditches	Pass			
Ditches	Pass					
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803258	URSA NTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175594