

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/13/2017

Submitted Date:

06/14/2017

Document Number:

680302010

FIELD INSPECTION FORM

Loc ID 304663 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 75027
Name of Operator: ROSEWOOD RESOURCES INC
Address: 2101 CEDAR SPRINGS RD STE 1500
City: DALLAS State: TX Zip: 75201

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------|---------------------|
| Krehmeyer, James | 970-848-2228 | jkrehmeyer@rosewd.com | Cell # 970-630-3880 |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 270448 | WELL | PR | 02/20/2004 | GW | 125-08833 | MCCONNELL 1-12 | PR |

General Comment:

[Routine Site Inspection](#)

Location

| | | | |
|--------------------|-----------------------------------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Located within irrigated cropland | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------------|--------------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | | Date: |

| | | | |
|----------------------------------|--------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|-------------|--|-------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Steel panel | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------------|---------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Prime Mover | # 0 | | |
| Comment: | Flowing | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|--|--|-------|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------|--|--|--|
| Flaring: | | | |
| Type | | | |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 270448 Type: WELL API Number: 125-08833 Status: PR Insp. Status: PR

Producing Well

Comment: [Flowing GW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other | In Process | Other | In Process | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401308426 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170322 |