

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2017

Submitted Date:

06/21/2017

Document Number:

687400064**FIELD INSPECTION FORM**Loc ID 335737 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 90615Name of Operator: TUDEX PETROLEUM INCAddress: UNIT E 2121 39TH AVENUE NECity: CALGARY State: AB Zip: T2E 6R7**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Conn, Lionel	1 40 3250 7225	tudorcorp@hotmail.ca	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203258	WELL	PR	08/01/2014	OW	001-08767	HI-LAND 10-B	PR
203259	WELL	PR	05/01/2015	OW	001-08768	HI-LAND 10-G	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: No emergency contact info at wellhead.

Corrective Action: Install sign to comply with Rule 210.b.

Date: 07/21/2017

Good Housekeeping:

Type	TRASH		
Comment:	Trash stored inside and outside of separator housing, and barrel at wellhead. See photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 07/03/2017
Type	OTHER		
Comment:	Stained soil in separator cabinet, see photos		
Corrective Action:			Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Chainlink around wellheads and pumping units.		
Corrective Action:			Date:

Equipment:

Type: Other	# 1		corrective date
Comment:	Circulation pump located in separator housing shed.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	#		
Comment:	LOCATED ON SEPARATOR EXHAUST		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Conventional		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Type: Prime Mover	# 1	
Comment:	Natural gas fired engine	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 203258 Type: WELL API Number: 001-08767 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____Facility ID: 203259 Type: WELL API Number: 001-08768 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: 07/11/2017**COGCC Comments**

Comment	User	Date
	kraicha	06/21/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400068	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4176179