

Inspection Photos  
Location Name: Iles Investment Co 1-23  
API: 05-081-05136



**Photo 1. Overview of location taken at entrance facing north.  
Unused riser cluster in foreground.**

Inspection Photos  
Location Name: Iles Investment Co 1-23  
API: 05-081-05136



Photo 2. Risers at wellhead. No wellhead sign.



Photo 3. Stained soil at tank base.



Inspection Photos  
Location Name: Iles Investment Co 1-23  
API: 05-081-05136



**Photo 4. Stained soil at tank base.**



**Photo 5. Stained soil at tank base.**

Inspection Photos  
Location Name: Iles Investment Co 1-23  
API: 05-081-05136



**Photo 6. Stained soil between tan tanks and pit in background.**



**Photo 7. Pit with unused riser and sagging netting. Oil in pit.**



Inspection Photos  
Location Name: Iles Investment Co 1-23  
API: 05-081-05136



**Photo 8. Pit with tanks in background.**



**Photo 9. Riser cluster, stained soil, unlabeled tanks.**