

Inspection Photos
Location Name: Horsetail #19N-1924M-R
API: 05-123-40630



Photo 1: Location, looking N



Photo 2: Wellhead, looking NW

Inspection Photos
Location Name: Horsetail #19N-1924M-R
API: 05-123-40630



Photo from prior inspection for comparison purposes



Photo 3: Stained soil remediated or removed



Inspection Photos
Location Name: Horsetail #19N-1924M-R
API: 05-123-40630



Photo from prior inspection for comparison purposes



Photo 4: Tanks labeled

