

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/20/2017

Submitted Date:

06/22/2017

Document Number:

685303399

### FIELD INSPECTION FORM

Loc ID 322089 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100178  
 Name of Operator: D J SIMMONS INC  
 Address: P.O. BOX 1469  
 City: FARMINGTON State: NM Zip: 87401

**Findings:**

- 22 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Byrom, John		jbyrom@djsimmons.com	<a href="#">All Inspections</a>
Seale, Rod		rseale@djsimmons.com	<a href="#">Pet. Eng./Operations Mgr</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208904	WELL	PR	03/01/2017	GW	033-06008	HUSKEY "B" UNIT 1	PR

**General Comment:**

[2017 Flowline NTO Inspection Statewide](#)

See link at end of report for path to downloadable pictures. Inspection report contains corrective actions and comment. See Good Housekeeping and Equipment sections of report for additional details.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Dirt and gravel two track road.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Labels directly on tanks.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Freestanding framed metal sign located at pad entrance.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Operator contact information on wellhead sign.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil and gravel at wellhead. Less than a 5 gallon bucket clean up.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Prime Mover	# 1		corrective date
Comment:	Natural gas motor.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	In use - Steel 3" line from separator oil dump outlet to oil tank battery. All points on location. 37.612/-108.993431 from scout card.		
Corrective Action:			Date:

Type: Flow Line	# 1		
Comment:	In use - Steel 3" line from separator outlet to gas meter inlet. All points on location. 37.612/-108.993431 from scout card.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	<p>In use - Steel 1" supply gas line from separator outlet to wellhead pump jack, oil tank battery and ?. All points on location. 37.612/-108.993431 from scout card.</p> <p>Not in use portion of 1" supply gas line appears to come up at tank battery pass through a regulator and back into the ground. Line does not appear to be in use and is not painted and tagged for abandonment or planned future use. NTO required this to be completed by May 30, 2017.</p> <p>No locate done to verify underground connections. Inspector and D J Simmons representative unable to determine all end points of supply gas line through visual inspection.</p>		
Corrective Action:	Comply with Phase I-Part 2 of the May 2, 2107 Flowline NTO.		Date: 05/30/2017
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	<p>Not in use - Return/recirculate line from tank battery to separator. Steel line off backside of tank is tied into under ground by a steel line that comes above ground to a pump that sends fluid back to separator. Not painted and tagged for abandonment or future use. No locate done to verify underground connections. Motor has been removed from pump. NTO required this to be completed by May 30, 2017.</p>		
Corrective Action:	Comply with Phase I-Part 2 of the May 2, 2107 Flowline NTO.		Date: 05/30/2017
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	In use - Steel 3" line from wellhead to separator inlet and swab line to produced water tank. All points on location. 37.612/-108.993431 from scout card.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		
Comment:	Above ground 200 BBL steel tank with earthen berms.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	OTHER	STEEL AST		
Comment: Above ground 465 BBL steel tanks with earthen berms.					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	465 BBLs	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 208904 Type: WELL API Number: 033-06008 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR - Review of electronic well file reflects last reported production as April 2017.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around production tanks.
Gravel	Pass	Gravel	Pass			
Comment: <input type="text" value="Stormwater BMPs appear to be functioning at time of inspection."/>						Date: _____
Corrective Action: <input type="text"/>						
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
Location piping is confusing and not all lines are in use and no locate has been done. Tie in descriptions are provided by D J Simmons representative as best to his knowledge. Lines need to be located and mapped for accurate identification of flowline end points to comply with May 2, 2017 Flowline NTO.	stjohnw	06/21/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303408	Wellhead sign.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177397">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177397</a>
685303409	Supply gas horseshoe at wellhead.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177398">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177398</a>
685303410	Supply gas at oil tank battery.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177399">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177399</a>
685303411	Recirculating line at oil tank battery.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177400">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177400</a>