

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/21/2017

Submitted Date:

06/22/2017

Document Number:

666803270

FIELD INSPECTION FORM

Loc ID 335539 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
 Name of Operator: URSA OPERATING COMPANY LLC
 Address: 1600 BROADWAY ST STE 2600
 City: DENVER State: CO Zip: 80202

Findings:

- 17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291673	WELL	PR	06/11/2013	GW	045-14477	MCPHERSON A3	PR
291679	WELL	PR	05/22/2012	GW	045-14475	McPherson A8	PR
291680	WELL	PR	06/11/2013	GW	045-14476	MCPHERSON A4	PR
298100	WELL	PR	05/17/2012	GW	045-17067	McPherson A6	PR
298101	WELL	PR	06/11/2013	GW	045-17068	MCPHERSON A9	PR
298102	WELL	PR	06/11/2013	GW	045-17069	MCPHERSON A2	PR
298103	WELL	PR	05/23/2012	GW	045-17070	McPherson A12	PR
298104	WELL	PR	05/25/2012	OW	045-17071	McPherson A11	PR
298105	WELL	PR	05/22/2012	GW	045-17072	McPherson A7	PR

General Comment:

[2017 Flowline NTO Inspection 1000' Buffer](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 9	Comment: 39.531079/-107.675684	Corrective Action:	Date:	
Type: Flow Line	#	Comment: Not in use 2-3", Marked with paint, see photo	Corrective Action:	Date:	
Type: Horizontal Heated Separator	# 9	Comment: 39.531254/-107.676370	Corrective Action:	Date:	
Type: Flow Line	#	Comment: In use; 9-2" steel risers at wellhead, 28-2", 5-3" risers at separators, 2-3", 1-1" risers at tanks, 1-1" gas feed to ECB	Corrective Action:	Date:	
Type: Emission Control Device	# 1	Comment: 39.530864/-107.675795	Corrective Action:	Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment: Centralized battery					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		39.530986,-107.676186
Comment:					
Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	291673	Type:	WELL	API Number:	045-14477	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	291679	Type:	WELL	API Number:	045-14475	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	291680	Type:	WELL	API Number:	045-14476	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	298100	Type:	WELL	API Number:	045-17067	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	298101	Type:	WELL	API Number:	045-17068	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	298102	Type:	WELL	API Number:	045-17069	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	298103	Type:	WELL	API Number:	045-17070	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	298104	Type:	WELL	API Number:	045-17071	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: 298105 Type: WELL API Number: 045-17072 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Sediment Traps	Pass			
		Ditches	Pass			
Berms	Pass					
Seeding	In Process					
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803275	URSA NTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177789
666803276	URSA NTO 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177790
666803277	URSA NTO 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177791