

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2017

Submitted Date:

06/22/2017

Document Number:

666803288

FIELD INSPECTION FORM

Loc ID 335276 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211376	WELL	PR	01/29/1997	GW	045-07136	GIBSON GULCH UNIT 2-31	PR
295341	WELL	PR	09/10/2008	GW	045-15730	GGU RODREICK 31A-31-691	PR
295344	WELL	PR	09/10/2008	GW	045-15733	GGU RODREICK 31D-31-691	PR
295345	WELL	PR	09/10/2008	GW	045-15734	GGU RODREICK 42D-31-691	PR
295346	WELL	PR	09/10/2008	GW	045-15735	GGU RODREICK 41A-31-691	PR
295347	WELL	PR	09/10/2008	GW	045-15736	GGU RODREICK 41C-31-691	PR

General Comment:

[2017 Flowline NTO Inspection 1000' Buffer](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Flow Line	#				
		In use; 6-2" steel risers at wellhead, 31-2", 3-1", 2-3" risers at separators, 2-3", 1-2", 1-1" risers at tanks, 8-2" risers at gas meter run, 1-1" gas feed to ECB			
Type: Plunger Lift	# 5				
		39.489175/-107.592645			
Type: Horizontal Heated Separator	# 8				
		39.488214/-107.592188			
Type: Plunger Lift	# 1				
		39.489417/-107.592577			
Type: Gas Meter Run	# 4				
		39.488105/-107.592192			
Type: Pig Station	# 1				
		39.488080/-107.592023			
Type: Pig Station	# 1				
		39.489308/-107.592062			
Type: Emission Control Device	# 1				
		39.488284/-107.592107			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLs	STEEL AST		39.488478,-107.592176

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211376	Type:	WELL	API Number:	045-07136	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	295341	Type:	WELL	API Number:	045-15730	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	295344	Type:	WELL	API Number:	045-15733	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	295345	Type:	WELL	API Number:	045-15734	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	295346	Type:	WELL	API Number:	045-15735	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	295347	Type:	WELL	API Number:	045-15736	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803289	NTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177862
666803290	NTO 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177863
666803291	NTO 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177864