

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/13/2017

Submitted Date:

06/16/2017

Document Number:

674901712

FIELD INSPECTION FORM

Loc ID 313609 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LP
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Millican, Chris		chris_millican@kindermorgan.com	
Chesson, Bob		robert.chesson@state.co.us	
Conway, James	970-882-5505	james_conway@kindermorgan.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Gintautas, Peter		peter.gintautas@state.co.us	
Swift, Barry	970-882-5545	barry_swift@kindermorgan.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292924	WELL	PR	06/26/2008	GW	083-06633	GOODMAN POINT 9	EI

General Comment:

On June 13, 2017 COGCC SW EPS collected produced water samples from the Kinder Morgan Goodman Point #9 at the Goodman Point Central Processing Facility. Kinder Morgan representatives Mike Hannigan and Brad Mustoe were present during the collection of water samples for the COGCC 2017 NORM Produced Water Study. Kinder Morgan collected split samples.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:				corrective date
Type: Flow Line	# 1			
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 292924 Type: WELL API Number: 083-06633 Status: PR Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: Other Comment: Separator

Sample	Sample Type: <u>PRODUCED</u>			
Time: <u>06/13/2017 09:30</u> (MM/dd/yyyy hh:mm)	GPS: Lat <u>37.405524</u>	Long <u>-108.792959</u>		
BTEX: _____	TPH: _____	Anion: _____	Captions: _____	General Chemistry: _____
Dissolved Methane: _____	Composition: _____	Stable Isotopes: _____	8260: _____	
8270: _____	RCRA Metals: _____	910-Metals: _____	PAH: _____	
Other: <u>2017 COGCC NORM Produced Water Study</u>				
Comment: <u>Samples collected from test separator within Goodman Point CPF.</u>				

Lab:

Lab Name _____
 ALS _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On June 13, 2017 COGCC SW EPS Jim Hughes collected produced water samples from the Kinder Morgan Goodman Point #9 at the Goodman Point Central Processing Facility. Kinder Morgan representatives Mike Hannigan and Brad Mustoe were present during the collection of water samples for the COGCC 2017 NORM Produced Water Study. Kinder Morgan collected split samples.</p> <p>A sample port was prepared by Kinder Morgan on piping from a test separator where produced water from the GP #9 well was isolated. Split samples were collected from ¼" stainless steel tubing. Samples were shipped to ALS for analysis.</p>	hughesj	06/16/2017

Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401311034	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172855
674901713	Sample port configuration.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172847
674901714	Sample port location on test separator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172848
674901715	Cubitainer sample collection.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172849