



**photo 1:** Facing east toward the access road.



**photo 2:** Facing east toward the location.



**photo 3:** Facing east at the location. There is a metal pipe at the center of the location.



**photo 4:** Facing south at the location. There is a metal pipe at the center of the location.



**photo 5:** There is wooden timbers and oil stained soil at the center of the location.



**photo 6:** There is cement blocks and fencing debris that remains at the location.



**photo 7:** Northeast side of the location facing southwest.



**photo 8:** There are noxious weeds (Canada thistle) around the northeastern side of the location.



**photo 9:** Facing east at tank battery site northwest of the well; Lat/Long:39.95737,-104.92150.



**photo 10:** Facing west at tank battery site northwest of the well; Lat/Long:39.95737,-104.92150.