



**photo 1:** Facing east toward the access road. Gravel remains along the road.



**photo 2:** There wood lumber debris that remains at the center of the location.





**photo 3:** South side of the location facing north.



**photo 4:** Facing west toward the access road.





**photo 5:** There are berms that remain at the former battery site at the northwest side of the location.



**photo 6:** North side of the location facing south.